

Item Code	Item Code Description. See drawing	Product Line	QtyAvail	Unit Price US\$
1188	FL2.5-E-150-10-20-1.5-2, VENT	PFX	1	\$100
1491NP	V522-304SS-150-79-22-999/20PS(PM1	1	
1532	PT8-SS-150-1-8NC-BNC	PM1	1	\$300
1637	V518-SS-150-26-20-3112PS (NP)	PM1	6	
1667NP	V522-SS-150-21-16-3112PS(NP)	PM1	2	
3501R	SP26/11-SS-150-9-26-M83513PS	PM1	2	\$350
3575	V512XL-AL-150-3/6-PC18/26-RCPT	PM2	1	\$300
3762-1	FL20/8-AL-150-2-TE24-PIN-2T	PM2	5	\$200
4094	V57-ZA-80-2-TZ26-BUTTON-13.8	PM2	3	\$150
0597-7	SP8L-E-150-9-TZ22-5-16	PSH	14	\$200
0597-8	SP8L-E-150-9-TZ22-70-70cm	PSH	2	\$200
1830	SPF12-E-150-2/4-TEE10/16-24-36	PSH	1	\$60
2131	SP8M-E-150-1TSJP-PE22-297-20	PSH	1	\$60
2390	SP8L-E-200UL94-2-TEE18-12-6	PSH	203	\$50
2390-3	SP8L-E-200UL94-2-TEE18-3.4-6	PSH	12	\$50
2476	SP11M-E-200UL94-2/2-TZ14/22-13	PSH	41	\$60
2501-1	SP6-E-150-4-TZ22-5-26	PSH	1	\$100
2624	SP8L-E-200UL94-2-TZ16-290-150m	PSH	55	\$50
2690-1	PT6-8-150-2/15P-TE18/TE26-30-4	PSH	4	\$70
2859	SP11M-E-200-18-TE24-6-24	PSH	1	\$200
2903	SPF12-E-150-1/4/12-RG188AU/TE2	PSH	1	\$300
2918-1	SP8L-E-200UL94-2-TZ16-200mm-20	PSH	3	\$50
2918-2	SP8L-E-200UL94-2-TZ16-500mm-50	PSH	14	\$50
3133	S08-SS-150-2-TE20-10-SC	PSH	1	\$140
3187	SP24-E-150-2/1/1-PC10/20RIB/16	PSH	100	\$150
3340-1	SP6X-E-200UL94-2-TE26-3-12	PSH	1	\$100
3589	SP8L-E-150-10-TK24-25-50CM	PSH	15	\$100
3635	SP8C-E-200UL94-2-TE18-2-21	PSH	6	\$50
3764	SP6L-E-200UL94-2-ETFE24-20-8,	PSH	71	\$100
4042	SP16-E-150-12-PC18-10-37	PSH	2	\$100
4087-1	SPF14-E-150-4-GXL12-32.9-14.2	PSH	5	\$60
4151	SP8M-E-150-2-IPC14-7-7	PSH	4	\$50
4195	SP8C-E-200UL94-2-TEE18-2-21	PSH	4	\$50
4216	SP16-E-200-12-TEE18-24-24, REV	PSH	1	\$150
4218	SP11/10-E-200UL94-2-TEE18-1-4	PSH	50	\$100
4492	SP11M-E-150-4-TZ14-24-24	PSH	3	\$100
4664	SP8C-E-200UL94-2-TZ14-4-10	PSH	9	\$50
4673	SPF14-E-150-4-GXL12-32.9T-14.2	PSH	9	\$100
4713	SP8M-E-200-12-TE28-200mm-200mm	PSH	6	\$120
4714	SPF12-E-150-21/3-PC26/TFCP015-	PSH	1	\$150
4773	SP6X-E-200UL94-2-TZ22-10-10	PSH	6	\$100
4872	SPF12W-E-150-16-TE28-18-18	PSH	2	\$150
4882	SP8L-E-150-7-E24-10-10	PSH	2	\$100
4887	SPF12-E-150-2/13/1-PC20/PC28/C	PSH	2	\$150
4966	SP9.3/4.6-E-150-2-TE14-2-38	PSH	2	\$100
4967	SPF12L-E-200UL94-3-TZ18-100-94	PSH	13	\$100
5045	SPF12-E-150-6-TZ18-21-8	PSH	10	\$150
5202-1	V515L-SS-200-4-TZ14-7-5	PSH	1	\$160
5352	V532-SS-150-99-TZ22-36-36	PSH	71	\$1,400
5464	SP11H-E-150-10-TZ22-50-50CM	PSH	3	\$350
5542	SP8L-E-150-7-TZ22-70-70cm	PSH	4	\$100
5552	V515L-AL-150-16P/8-KT28/TE26-1	PSH	1	\$500
5786	V522-SS-150HV-1-HVPC20-15-13	PSH	1	\$300
STK #24	2030, V522-E-150-PLUG Solid pl	STK	1	\$100
STK #24A	2189-11 wire, SP16-E-150-11-TE	STK	1	\$100
STK #25	4664R, SP8C-E-200UL94-2-TZ14-1	STK	178	\$50
STK #25A	#3205-7, FL54/18-AL-150-7-RG17	STK	1	\$600
STK #26	5138X, SPF12LTC-E-150-2/4-TZ16	STK	131	\$50
STK #26A	2411-X, PTZ-SS-150-4-TE24-12-1	STK	2	\$100
STK #26B	2633, SP6-E-150-2-TE22-12-12	STK	10	\$100
STK #27	#4839-7X, PT12-SS-150-7P-TT20-	STK	1	\$400
STK #27A	4583-1R, CF275-SS-150-10-RG188	STK	1	\$1,600
STK #28	2316-9X, SP11L-E-150-9-TE24-60	STK	1	\$100
STK #30A	#1518-1-BLK	STK	5	\$300
STK #30B	4982-X, 51 pin @ 94.3 angle	STK	1	\$500
STK #31	2035-1R, V58-SS-150-1P-SX20TWS	STK	1	\$200
STK #32A	1701, V515L-SS-150-29-TE30-600m	STK	1	\$400
STK #33A	1667X-20--Pin X has no continu	STK	1	\$900
STK #34	5090X, Wire color loc. wrong	STK	1	\$200
STK #35	3536R, CONXALL-150-2/2/11/1-PC	STK	4	\$250
STK #35A	1588-8X-PT8-SS-150-8-TZ22	STK	1	\$200
STK #36A	3187, SP24-E-150-2/1/1-PC10/20	STK	30	\$50
STK #37A	4490--43 fibers (43 good fibe	STK	2	\$300
STK #37B	4983-X, Pin Conn.@ 93.5 angle	STK	1	\$900
STK #38A	3830X, SPF18-E-200-1-TST22-100	STK	6	\$100
STK #39	1733, SPF18-E-150-30-TZ22-15-1	STK	18	\$200
STK #40	2390- short wires 11-5.5"	STK	6	\$50
STK #46A	4709X, SP16-E-150-3/4-TZ14/20-	STK	2	\$100
STK #50	4714X, 1 missing PC26 wire	STK	1	\$150
STK #65	5142X,-thermal cyc- new temp r	STK	1	\$200
STK #65A	5140X Old desgin w/o butt spli	STK	2	\$250
STK #66	1667X, V522-SS-150-20-3112PS:	STK	1	\$900
STK #67	4464X, V526-SS-150-36-22-27472	STK	1	\$1,100
STK #67A	1491X, V522-304-SS-150-78-22-9	STK	1	\$1,900
STK #69	1398, SP5-P-150-2-TEE26-2-15--	STK	7	\$100
STK #76	2567-1, V58N-SS-150-1-MMFO-SNA	STK	33	\$400
STK #76B	2843-1, SNAP-LOCK FO PLUG PATC	STK	33	\$300
STK #77A	2064-X, S08-SS-150-3-TEE24-24-	STK	1	\$100
STK #78	4618X, SP9-E-200UL94-2-PTFE16-	STK	7	\$50
STK #79A	#3232-X, SP16/G-AL-150-14-26-1	STK	1	\$500
STK #80	3935X, SPF12XL-E-200-4-TEE12-1	STK	15	\$300
STK #81	4006X, SPF12XL-E-200-1-2TSP24-	STK	3	\$200
STK #84	3527-X, He leak=1 X10^-6 Per N	STK	1	\$300
STK #85	5656 13 pairs type T #26 wires	STK	1	\$800
STK #85A	5587-X-PT12-SS-200HV-.5CU-2-1.	STK	3	\$500
STK #85B	3567NP-X, V526-SS-150-127-22-9	STK	2	\$2,000
STK #86	4740X, SP8S-E-200-6-TZ22-10-6	STK	6	\$200
STK #87	5464-X-10K psi no twist or sal	STK	10	\$700
STK #89	2316X, SP11L-E-150-10-TE24-60-	STK	9	\$90